

Message

---

**From:** Lobik Stephen [slobik@facil.umass.edu]  
**Sent:** 6/23/2011 12:24:36 PM  
**To:** Roger Jarosz [rjarosz@ingledc.com]  
**CC:** Pocsik Mark [mpocsik@facil.umass.edu]; Hanchett, James (DPH) [/O=COMMONWEALTH OF MASSACHUSETTS/OU=MassMail-01/cn=Recipients/cn=James.Hanchett]  
**Subject:** RE: DPH

Thanks Roger.

Jim doors working OK?

I think the floor is a UMA problem. When will the ceiling be repaired? Please let us know.

Thanks,

Stephen

Stephen Lobik  
Capital Project Manager  
Facilities Planning Division  
University of Massachusetts  
(T) 413-545-6516  
(C) [REDACTED]  
(F) 413-545-3684  
slobik@facil.umass.edu

**From:** Roger Jarosz [mailto:rjarosz@ingledc.com]  
**Sent:** Wednesday, June 22, 2011 4:22 PM  
**To:** Lobik Stephen  
**Cc:** Pocsik Mark  
**Subject:** RE: DPH

Steve/Mark:

#`s 1,2,5 were complete as of your writing. All doors are functioning properly and the silencers have been installed. I confirmed this with Jim today.

I am not sure what to do about the moisture coming through the VCT seams, I believe there is a duct chase below that portion of the floor which may be contributing to the moisture, We will continue to try to ascertain the problem.

Roger Jarosz  
Inglewood Development Corp

**From:** Lobik Stephen [mailto:[slobik@facil.umass.edu](mailto:slobik@facil.umass.edu)]  
**Sent:** Wednesday, June 15, 2011 1:15 PM  
**To:** Roger Jarosz  
**Cc:** Pocsik Mark  
**Subject:** FW: DPH

Roger,

Please see Mark's note along with the attached plan. Please let me know when these items are taken care of.

Thanks,

Stephen

Stephen Lobik  
Capital Project Manager  
Facilities Planning Division  
University of Massachusetts  
(T) 413-545-6516  
(C) [REDACTED]  
(F) 413-545-3684  
[slobik@facil.umass.edu](mailto:slobik@facil.umass.edu)

**From:** Pocsik Mark  
**Sent:** Wednesday, June 15, 2011 12:39 PM  
**To:** Lobik Stephen  
**Subject:** DPH

Steve, see attached drawing:

1. Back check needs to be adjusted
2. Door won't close, rubbing on VCT
3. Moisture coming through VCT seems
4. Need to replace a 2ft. piece of ceiling grid
5. Missing door silencers

Mark

Mark S. Pocsik  
*Construction Engineer*  
*Facilities Planning*  
*University of Massachusetts*  
*360 Campus Center Way*  
*Amherst, Ma. 01003-9248*  
*Office: 413-577-1713*  
*Cell: [REDACTED]*  
*Fax: 413-545-3684*

